



Software Release Note for STA

This document is property of Ralink Technology, Inc. Transmittal, receipt, or possession of this document does not express, license, or imply any rights to use, sell, design, or manufacture from this information or the software documented herein. No reproduction, publication, or disclosure of this information, in whole or in part, shall be allowed, unless the prior written consent of Ralink Technology, Inc. is obtained.

NOTE: THIS DOCUMENT CONTAINS SENSITIVE INFORMATION AND HAS RESTRICTED DISTRIBUTION.

Product Name	RT2870 Wireless Card
Interface Supported	USB
Install Package Version	RTUSB D2870-4.1.5.0 UI-4.0.5.0_2011_07_21.dmg
RT28xx Driver Version	4.1.5.0
User Interface Version	4.0.5.0
Date	2011-07-21

System Requirement:

Mac OS X 10.6.X or 10.5.X or 10.4.X

Hardware Supported:

Ralink RT2870/RT3070/RT3071/RT3072/RT3052 chipset USB

Software Supported:

For Mac OS X 10.6.X:

USBWireless -10.6\ USBWireless -SnowLeopard.pkg

For Mac OS X 10.5.X:

USBWireless -10.5\ USBWireless -Leopard.pkg

For Mac OS X 10.4.X:

USBWireless -10.4\ USBWireless -Tiger.pkg

Release History:

[RTUSB D2870-4.1.5.0 UI-4.0.5.0 2011_07_21.dmg](#)

UI - V.4.0.5.0

1. Limited Certification number to 128.
- 2.

[RTUSB D2870-4.1.5.0 UI-4.0.4.0 2011_07_18.dmg](#)

Driver - V.4.1.5.0

1. Remove some setting in message function.

UI - V.4.0.4.0

3. Fixed UI crashed problem when WPS rescan in RescanTimeEnd.

[RTUSB D2870-4.1.4.0 UI-4.0.3.0 2011_06_21.dmg](#)

Driver - V.4.1.4.0

2. Fixed WPA2-PSK/AES/TKIP connection problem on MAC OS 10.4.

[RTUSB D2870-4.1.3.0 UI-4.0.3.0 2011_06_17.dmg](#)

Driver - V.4.1.3.0

3. Fixed crash caused by spin lock deadlock.
4. Fixed remove key too late when connect to WPA2-PSK/AES AP.

UI - V.4.0.3.0

4. Fixed profile can't fill hidden SSID.
5. Changed text of Radio Switch button.

[RTUSB D2870-4.1.2.0 UI-4.0.2.0 2011_06_13.dmg](#)

1. Update PID/VID only.

[RTUSB D2870-4.1.2.0 UI-4.0.2.0 2011_05_02.dmg](#)

Driver - V.4.1.2.0

1. Fixed RT3572 with HW PBC's GPIO problem. Register wrote wrong value.

[RTUSB D2870-4.1.1.0 UI-4.0.2.0 2011_03_29.dmg](#)

Driver - V.4.1.1.0

1. Fixed crashed problem when setting WDS type in mbuf.

[RTUSB D2870-4.1.0.0 UI-4.0.2.0 2011 03 25.dmg](#)

[Driver - V.4.1.0.0](#)

5. Supported RT5370.

[UI - V.4.0.1.0](#)

6. UI crashed with setting security.

[UI - V.4.0.2.0](#)

1. RTS Threshold setting wrong initial value.

[RTUSB D2870-4.1.0.0 UI-4.0.0.0 2011 02 11.dmg](#)

[Driver - V.4.1.0.0](#)

6. Supported RT3573.

[Driver - V.4.0.0.0](#)

1. Supported SoftAp.

[UI - V.4.0.0.0](#)

2. Supported SoftAp.

[RTUSB D2870-3.0.3.0 UI-3.0.0.0 2010 09 17.dmg](#)

3. Update CommandServer.

[RTUSB D2870-3.0.3.0 UI-3.0.0.0 2010 09 10.dmg](#)

[Driver - V.3.0.3.0](#)

4. Fixed WPA-PSK/WPA2-PSK Handshake function fro group key.

5. Fixed Scutum can't connect when reboot.

[Driver - V.3.0.2.0](#)

1. Fixed WPS LED MODE 8 when turn off Radio.

2. Fixed group key hasdshake when rekey problem of TKIP.

3.

[Driver - V.3.0.1.0](#)

Added VCO calibration.

[RTUSB D2870-3.0.0.0 UI-3.0.0.0 2010 05 12.dmg](#)

1. Fixed ScutumServer problem on MAC OS 10.5.X.

RTUSB D2870-3.0.0.0 UI-3.0.0.0 2010_04_06.dmg

1. First Release. It' s a new install package for RaUI + API + Scutum. Scutum only supported on MAC OS 10.5.x and 10.6.x.